

6/30/72

Rule 62. Hazardous Materials.

No hazardous materials shall be discharged from any source so as to result in concentrations at or beyond the property line in excess of any State, Federal or local standards or emission limits established.

In the absence of specific standards for particular hazardous material, the air borne concentrations of such materials shall not exceed those levels and time intervals established by the State Division of Industrial Safety or the Occupational Safety and Health Administration.